

x1




x2



x4



x4



17



13




T40




Ø 7 mm




Ø 10 mm

1**2**


3



2x



2x




4

Ø 7 mm



10x50




Ø 10 mm



M10x60

**5**


5




6




7




8



9



9**10**