

x1





x2



x6





x6




Ø 7 mm




Ø 10 mm

1**2**


3



2x



2x




4

Ø 7 mm




10x50




Ø 10 mm




M10x60

**5**


5




6




7




8



9



9**10**